

**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY
CONDITION CERTIFICATE**


No. 187.....

Date 3-2-2018.

It is certified that an inspection team headed by Ashok Mukati
SDO (Name of officers with designation) from Public Health Engineering
 Department PHE Sub Dn Damoh (Name of Department/Office) inspected the --
St. John's Senior Sec. School Damoh (M.E.) on 3.2.2018
 -and found that the St. John's Senior Sec. School Damoh has safe drinking water
 facilities for the students and members of staff of the institution and maintaining
 the hygienic sanitation condition in the school building & the campus as per the
 norms prescribed by the central/State/U.T.Govt.


The above valid for a period of 1 Year (3.2.2018-19)


 Assistant Engineer
 P.H.E. Sub. Division
 Damoh

Signature with seal: 
 Executive Engineer
 P.H.E. Dn. DAMOH

Name: K.S. Panwar

Designation: EEP.H.E.D. Damoh


 PRINCIPAL
 ST. JOHN'S SR. SEC. SCHOOL
 JABALPUR NAKA, DAMOH

कार्यालय सहायक यंत्री, लोक स्वा० यां० उपखंड दमोह

कं. 1727 / प्र.शा. / स. य. / लोक स्वा. यां. / उपखंड / दमोह / दिनांक 23/10/17
प्रति,

प्रिंसिपल

सेन्टजोन्स सीनियर सेकेंडरी स्कूल


जवलपुरनाका दमोह

विषय :- जल परीक्षण रिपोर्ट बावत।

संदर्भ :- आपका पत्र कं.1590 दिनांक 18/10/2017

उपरोक्त विषयांतर्गत लेख है कि आपके संदर्भित पत्र के द्वारा भेजे गये जल नमूने का परीक्षण कर जल परीक्षण रिपोर्ट अवलोकानार्थ हेतु प्रेषित है।

सहपत्र :- 1. रिपोर्ट प्रपत्र एक प्रति
2. एम. आर. रसीद


सहायक यंत्री,

लोक स्वा० यां० उपखंड दमोह
Catali


PRINCIPAL

ST. JOHN'S SR. SEC. SCHOOL
JABALPUR NAKA, DAMOH